



## **EtherWAN Managed Switch**

Firmware Release Notes

Copyright 2023 (c) EtherWAN Systems, Inc.

### **RELEASE SUMMARY**

Version: 2.02.9.7

Release Date: Jan. 16th, 2023

### **SUPPORTED PRODUCTS**

EX78900 Series	EX73900 Series	EX77900 Series
EX83000 Series		

### **ENHANCEMENTS**

1. Removed unnecessary MSTP Hello Timer timeout messages and IPv6 messages of Linux ntpd service from the device log.

### **BUG FIXES**

1. [System][MSTP] When there were more than one MSTP region in the network and the topology changes occurred, MAC flapping might occur.
2. [QoS] [Web/CLI] QoS Policy Strict + WRR did not function properly.
3. [VRRP] Abnormal high CPU usage might occur in some scenarios if ARP or VRRP protocol was interfered with by unknown L3 unicast packets.
4. [System] After the firmware upgrade, there were chances that the setting of the default gateway on the switch might fail, causing the loss of connection to the device.



## **EtherWAN Managed Switch**

Firmware Release Notes

Copyright 2022 (c) EtherWAN Systems, Inc.

### **RELEASE SUMMARY**

Version: 2.02.9.4

Release Date: April. 21st, 2022

### **SUPPORTED PRODUCTS**

EX78900 Series	EX73900 Series	EX77900 Series
EX83000 Series		

### **BUG FIXES**

1. [QoS] The VLAN priority of the traffic that is forwarded by the switch will be modified when the switch sets the queue of the VLAN priority in CoS.



## **EtherWAN Managed Switch**

Firmware Release Notes

Copyright 2022 (c) EtherWAN Systems, Inc.

### **RELEASE SUMMARY**

Version: 2.02.9.3

Release Date: Jan. 28th, 2022

### **SUPPORTED PRODUCTS**

EX78900 Series	EX73900 Series	EX77900 Series
EX83000 Series		

### **NEW FEATURES**

**1. [Security] Add Secure FTP (SFTP) for firmware update and configuration file upload/download.**

### **BUG FIXES**

1. [STP] While running MSTP, a new root event might occur due to some missing STP BPDU.
2. [OSPF] After configuring interface VLAN, VRRP, and OSPF, an OSPF interface configuration error might occur on the web GUI.
3. [Static MAC Entry] Cannot set MAC addresses under Static MAC Entry Discard successfully; the associated VLAN will be changed to VLAN 1 incorrectly after reboot.
4. [SNMP] SNMP server's Login Trap and Logout Trap did not work properly.
5. [SNMP] After setting one ring-coupling port, users cannot get the correct port status via SNMP.
6. [LLDP] LLDP Ports Settings and LLDP Statistics were incorrect via CLI.
7. [IGMP Snooping] When IGMP Snooping was disabled, there was a chance that multicast stream was forwarded to the router port incorrectly.
8. [STP] Remove new root trap and modify the system event.
9. [SNMP] When MAC notification traps are triggered, the memory allocation is incorrect.



## **EtherWAN Managed Switch**

Firmware Release Notes

Copyright 2021 (c) EtherWAN Systems, Inc.

### **RELEASE SUMMARY**

Version: 2.02.8.2

Release Date: March. 25th, 2021

### **SUPPORTED PRODUCTS**

EX78900 Series	EX73900 Series	EX77900 Series
EX83000 Series		

### **NEW FEATURES**

- 1. Added SNMP group feature for SNMPv3.**
- 2. Allowing special characters (i.e. “!” and “#”) to be used in authentication and privacy password.**
- 3. Support for AES-128/192/256 encryption in SNMPv3.**
- 4. Support for SNMPv3 Traps.**

### **BUG FIXES**

- 1. [IP] Fixed issue where ports with VLAN mapping links going down caused the default gateway information to be neglected from the running-config file.**
- 2. [MSTP][CLI] Corrected an MSTP digest calculation error that would cause some unwanted MSTP regions to be incompatible with other switches.**



## **EtherWAN Managed Switch**

Firmware Release Notes

Copyright 2020 (c) EtherWAN Systems, Inc.

### **RELEASE SUMMARY**

Version: 2.02.7.6

Release Date: Nov. 27th, 2020

### **SUPPORTED PRODUCTS**

EX78900 Series	EX73900 Series	EX77900 Series
EX83000 Series		

### **NEW FEATURES**

- 1. Added OSPF distribute-list feature - allows filtering routes from the routing table.**

### **BUG FIXES**

1. [System] Previously was unable to save configuration information into EB-232 dongle.
2. [Telnet] After several attempts at Telnet connection, some switches could not be accessed through either Telnet or SSH.



## **EtherWAN Managed Switch**

Firmware Release Notes

Copyright 2020 (c) EtherWAN Systems, Inc.

### **RELEASE SUMMARY**

Version: 2.02.7.3

Release Date: Oct. 21th, 2020

### **SUPPORTED PRODUCTS**

EX78900 Series	EX73900 Series	EX77900 Series
EX83000 Series		

### **NEW FEATURES**

- 1. Add Storm Detect Trap only feature.**
- 2. Add force change password when the default password is not set.**

### **ENHANCEMENTS**

1. The convergence time of MSTP with 3rd party switch takes too long to be completed once the disconnected link is restored.

### **BUG FIXES**

1. [MSTP & VRRP] The ping command may be lost or unable to reach to the switch under certain MSTP and VRRP configuration environments.
2. [MSTP & VRRP] The switch is unable to deliver VRRP advertisement packets due to MSTP paths of instance being sent incorrectly under certain MSTP and VRRP configuration environments.
3. [MSTP] When MSTP topology change occurs and a long convergence time results in a high latency response under certain MSTP environments.
4. [Flow Control] When Flow Control is set to off (1G Fiber Port), the action of flow control is actually opened.



## **EtherWAN Managed Switch**

Firmware Release Notes

Copyright 2020 (c) EtherWAN Systems, Inc.

### **RELEASE SUMMARY**

Version: 2.02.6.4

Release Date: March 27, 2020

### **SUPPORTED PRODUCTS**

EX78900 Series	EX73900 Series	EX77900 Series
----------------	----------------	----------------

### **NEW FEATURES**

- 1. Add the "Radius User Login" feature.**
- 2. Add the "Save log to flash" feature.**

### **BUG FIXES**

1. If the configuration of the ring-coupling has been changed, the ring-coupling port might have an incorrect port state in the bcm-shell after the topology change.
2. In MAC-Auth, all interfaces can't be authenticated after unplugged/plugged.
3. "Ingress" and "Egress" of port is back to default setting after DUT rebooting.
4. Cold Start: One of the Switch will auto reboot after the error message is displayed.
5. Lease time of DHCP Server is incorrect



## **EtherWAN Managed Switch**

Firmware Release Notes

Copyright 2019 (c) EtherWAN Systems, Inc.

### **RELEASE SUMMARY**

Version: 2.02.3

Release Date: August 12, 2019

### **SUPPORTED PRODUCTS**

EX78900 Series	EX73900 Series	EX77900 Series
----------------	----------------	----------------

### **BUG FIXES**

**Fixed:** When user upgraded to new firmware, the IP default-gateway was removed in running-config





## EtherWAN Managed Switch

Firmware Release Notes

Copyright 2019 (c) EtherWAN Systems, Inc.

### RELEASE SUMMARY

Version: 2.02.1

Release Date: 2019, Jan 7

### SUPPORTED PRODUCTS

EX78900 Series	EX73900 Series	EX77900 Series
----------------	----------------	----------------

### NEW FEATURES

#### 1.Added PoE watchdog

PoE Watchdog is a management feature to help system administrators monitor and manage critical PoE powered devices. PD Watchdog is only supported on PoE enabled ports. Once enabled, the system will continuously ping a user specified IP address across the port. If the system does not receive a reply within a specified interval, it can automatically power down or power cycle the powered device.

New CLI Commands: poe watchdog

Enable	PoE watchdog enable
failure-action	Action to take if check fails
	- No action
	- Power cycle (reboot PD)
	- Power off
max-failure-count	PoE Device check failure count
ping-interval	Ping interval
startup-delay	PoE Device startup delay check time
target-address	Failure check IP

#### 2.EX78900 only: PoE can be extended to 250m with 10Mbps transfer speed

When the extend mode is enabled, single POE port supports 250m transmission distances and 10Mbps speed

New CLI Commands: poe extend-mode enable

#### 3.Added MAC-Based Authorization

New CLI commands: auth-mac system-auth-control

auth-mac username-format UPPERCASE

#### 4.Added LLDP for Media Endpoint Device

New CLI commands:lldp med-tlv-select location  
location civic-address  
location coordinate  
location ecs-elin

#### **5.Added IPv6 Addressing, Route and DHCPv6 Server**

New CLI Commands: ipv6 address  
get ipv6 dhcpv6 enable  
dhcpv6-server enable  
dhcpv6-server range  
dhcpv6-server lease-time  
ipv6 forwarding  
ipv6 mroute  
ipv6 neighbor  
ipv6 route

#### **7.Added Display the Device Serial Number**

New CLI command: show serial number

#### **8.Added EEE (Energy-Efficient Ethernet) setting is configurable (Enable / Disable )**

New CLI commands: eee enable

### **MISCELLANEOUS CHANGES**

- 1. Flow control is now turned off as default**
- 2. STP auto-edge is now disabled as default**
- 3. LLDP is now enabled by default**

### **BUG FIXES**

- 1. Fix for a Radius interop issue with Cisco ISE, increasing the radius state from 48 to 256 characters**



## EtherWAN Managed Switch

Firmware Release Notes

Copyright 2017 (c) EtherWAN Systems, Inc.

### RELEASE SUMMARY

Version: 2.01.2

Release Date: 2017/Nov/1

### SUPPORTED PRODUCTS

EX78900 Series	EX73900 Series	EX77900 Series
EX78921B Series	EX78921R Series	

### BUG FIXES

**Fixed:** EX77900: Web Display of port numbers (xe1 thru xe4) are incorrectly shifted at Per Port VLAN Activities.

**Fixed:** EX77900: Set combo ports (Ge17-Ge24) 1Giga port to 100M/FD. Saving configuration and rebooting will cause SFP ports become disconnected.

**Fixed:** EX78900/EX73900: Set 1G copper Giga port(Ge1~Ge12) to 100M/FD, after saving configuration and rebooting bandwidth is incorrectly changed back to 1G.



## EtherWAN Managed Switch

Firmware Release Notes

Copyright 2017 (c) EtherWAN Systems, Inc.

### RELEASE SUMMARY

Version: 2.01.1

Release Date: 2017/Sep/12

### SUPPORTED PRODUCTS

EX78900 Series	EX73900 Series	EX77900 Series
EX78921B Series	EX78921R Series	

### NEW FEATURES

**1. Added Routing protocols**

Static routing

RIP V1/V2

**2. Added Routing redundancy protocol**

VRRP

**3. Added PoE force mode on EX78900 series**

New CLI Commands:

To display the device's model number:

CLI Command Mode: **Privileged Exec Mode**

**Enable poe force mode globally**

To enable poe force mode, use the following CLI command:

CLI Command Mode: Global config

CLI Command Syntax: [no] poe force-power enable

**Enable poe force mode on a port**

To enable poe force mode, use the following CLI command:

CLI Command Mode: Interface config

CLI Command Syntax: poe force-power on

no poe force-power

### BUG FIXES

**Fixed:** Fixed the GVRP Applicant to run in Active mode on a port, the GVRP protocol will not send out any PDUs from a port if the port is being blocked by STP

**Fixed:** After joining a multicast group, the multicast stream was not being forwarded to receivers after 30 seconds even the receivers tried re-joining the same multicast group afterwards

**Fixed:** The pre-assigned Class of Service (CoS) priority value was altered in tagged frames

**Fixed:** Rebooted a switch would cause it to reboot if Multiple Spanning Tree Protocol (MSTP) and Port Aggregation had been configured.