



EtherWAN Managed Switch

Firmware Release Notes

Copyright 2020 (c) EtherWAN Systems, Inc.

RELEASE SUMMARY

Version: 2.02.6.4

Release Date: March 27, 2020

SUPPORTED PRODUCTS

EX83304 Series		
----------------	--	--

NEW FEATURES

1. Add the "Radius User Login" feature.
2. Add the "Save log to flash" feature.

BUG FIXES

1. If the configuration of the ring-coupling has been changed, the ring-coupling port might have an incorrect port state in the bcm-shell after the topology change.
2. In MAC-Auth, all interfaces can't be authenticated after unplugged/plugged.
3. "Ingress" and "Egress" of port is back to default setting after DUT rebooting.
4. Cold Start: One of the Switch will auto reboot after the error message is displayed.
5. When user upgraded to new firmware, the IP default-gateway was removed in running-config.
6. Lease time of DHCP Server is incorrect